




Photograph 1
Existing entrance to Non-Motorized Boating area, looking north toward Building 11 from NOAA Access Road.




Photograph 2
Overview of the southeastern section of NSRA, with Building 27 in the distance.



Photograph 3
Timber rail and concrete bulkhead located along the shoreline adjacent to the tarmac area.



Photograph 4
Existing overwater structures: Pier 1, Building 31, and the floating boathouse.



Photograph 5
Existing overwater structures: the floating boathouse and floating docks.



Photograph 6
Existing overwater structure: the small pier.



Photograph 7
Overview of the northeastern section of NSRA.



Photograph 8
Existing shelter and picnic area.



Photograph 9
Concrete block bulkhead located along shoreline west of Pier 1.



Photograph 10
Seattle Public Utilities storm water outfall; Building 275 is in the background



Photograph 11
Typical substrate along the shoreline of NSRA.